Oil Field Environmental Incident Summary

Incident: 20150323151651 Date/Time of Notice: 03/23/2015 15:16

Responsible Party: LIBERTY RESOURCES MANAGEMENT COMPANY, LLC

Well Operator: LIBERTY RESOURCES MANAGEMENT COMPANY, LLC

Well Name: GOHRICK 158-95-17-8 CTB

Field Name: MCGREGOR Well File #:

Date Incident:3/22/2015Time Incident:13:30Facility ID Number:228439-01County:WILLIAMSTwp:158Rng:95Sec:17Qtr:SE SW

Location Description: spill was located at the remote Leon Central Facility located approximately

1800 feet to the west of the Gohrick wells that it services

Submitted By: tappan souther Received By:

Contact Person: tappan souther

1200 17TH STREET, SUITE 2200

DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 2 Barrels 2 Barrels

Brine

Other

Description of Other Released Contaminant:

Oil was sent to flare causing ~2 bbls of oil mist on ground. black smoke through flare and small fire on pad. no personnel injury or equipment damage

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

none

Areal Extent:

all oil was contained on location

Potential Environmental Impacts:

none

Action Taken or Planned:

Within minutes field personnel arrived on location and unloaded fluid packed vessel via a bypass to the dump valve that failed. Oil was eliminated to the flare and production resumed under normal conditions/operations under manned supervision. Spill was contained on location and clean up began immediately. Currently reviewing automation and valve selection to determine if a design change needs to be made. John Axtman was notified of spill via phone at 9:30 AM on 3/23/15.

Wastes Disposal Location: commercial disposal

Agencies Involved:

		te	

Date: 3/23/2015 Status: Reviewed - Follow-up Required Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted the surrounding area. Followup is necessary.

Date: 5/8/2015 Status: Inspection Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 13:59 4/28/2015.

This spill occurred at an active drill location. There are no signs of impacts off of location.

No followup is necessary.